

**SECRET**

Declassification Review by NGA/DoD

**OUT55226****SECRET 120011Z**

1965 MAR 12 00 23Z

25X1

1. CAMERA B-122 WAS USED IN MISSION 3993 FLOWN ON 9 MARCH 1965; 12 MAR 1965  
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND RESOLUTION GOOD.

B. 9R SIDE: EDGE FOG IS PRESENT INTERMITTENTLY ALONG THE  
OUTBOARD EDGE. MINUS DENSITY DOTS OCCUR 4.6 INCHES FROM THE INBOARD  
EDGE 1.55 INCHES APART, FROM FRAME 1 TO 138. ON FRAME 139 THE MINUS  
DENSITY DOTS BECOME 2.32 INCHES APART AND CONTINUE THROUGH THE FIRST  
HALF OF THE MISSION. THE CAMERA NUMBER IN THE DATA CHAMBER IS  
DIFFICULT TO READ. HEAT SPLICES ARE LOCATED ON FRAMES 1227, 1690,  
AND 2522. A MANUFACTURING SPLICE IS PRESENT ON FRAME 747. FOG  
VARYING DEGREES IS PRESENT ON FRAME 2522 TO 2529.

COPIES RECEIVED		
CyNo.	Office	Act
1	Master File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	TID	
	PAG	
	CIA/PID	
	DIAX #4	
	SPAD	
	NSA LO	
	DIAAP	
	Destroyed	

C. 9L SIDE: MINUS DENSITY DOTS OCCUR 4.15 INCHES AND 0.7  
INCHES FROM THE INBOARD EDGE THROUGHOUT THE FIRST PART OF THE MISSION.  
NUMEROUS PINHOLES ARE LOCATED ON FRAME 926. NUMEROUS PROCESSING  
STREAKS, PARALLEL TO THE MAJOR AXIS OF THE FILM, START ON FRAME  
925 AND CONTINUE THROUGHOUT THE REMAINDER OF THE MISSION. PROCESSING  
STREAKS PARALLEL TO THE MINOR AXIS OF THE FILM, UP TO 0.5 INCHES  
WIDE, OCCUR INTERMITTENTLY FROM FRAME 925 TO THE END OF THE MISSION.  
A HEAT SPLICE IS PRESENT ON FRAME 1249 AND A MANUFACTURING SPLICE  
ON FRAME 579.

D. BOTH SIDES: EDGE STATIC OF VARYING DEGREES OCCURS ALONG

**SECRET**

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

25X1

-2-

BOTH EDGES OF BOTH SIDES THROUGHOUT THE MISSION. MODE I WAS USED DURING THIS MISSION FROM FRAME 1 TO 276. MODE V WAS USED FROM FRAME 277 TO THE END OF THE MISSION. THE VERTICAL INDICATOR LIGHTS FAILED INTERMITTENTLY ON BOTH SIDES DURING THE MISSION. THE LAST TITLED FRAME IS 2532.

E. THERE WERE NO MAJOR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 35 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--